

CARE & CLEANING

Baths, Showers & Whirlpools
Made of Vikrell®

Inspired by the realities of life.

STERLING.

A KOHLER COMPANY



CARE & CLEANING

Baths, Showers & Whirlpools

Made of Vikrell®



STERLING® baths, showers and whirlpools are constructed from solid Vikrell material for superior strength and durability. Color-molded throughout, bath and shower products made of Vikrell also feature a smooth, seamless appearance and are easy for one person to transport and install.

GENERAL CARE & CLEANING

For best results, keep the following in mind when caring for STERLING product:

Test First – Always test your cleaning solution on an inconspicuous area before applying to the entire surface.

Wipe Clean – Wipe surfaces clean and rinse completely with water immediately after applying cleaner. Rinse and dry overspray that lands on nearby surfaces.

Don't Let Cleaners Soak – Do not allow cleaners to sit or soak.

Avoid Abrasive Materials – Use a soft, dampened sponge or cloth. Never use an abrasive material such as a brush or scouring pad to clean surfaces.

HOW TO CARE FOR YOUR BATHS, SHOWERS & WHIRLPOOLS MADE OF VIKRELL

Do not use abrasive cleansers or acidic solvents on Vikrell surfaces as they may cause surface dullness or discoloration.

Wipe your bath or shower unit with a soft cloth after each use to prevent a buildup of soap and scum.

Extreme heat such as that generated by cigarettes or portable heaters can damage Vikrell surfaces. Do not use such items near your bath or shower unit.

HOW TO FLUSH YOUR WHIRLPOOL SYSTEM

Flush your whirlpool system twice a month or more, depending upon usage.

Adjust the jets fully clockwise so there is no air induction.

Fill the bath with warm water to a level 2" above the highest jets, or leave water in the bath after using.

Add two teaspoons of a low-foaming powder automatic dishwasher detergent and 20 ounces of household bleach (5% -6% sodium hypochlorite) to the water.

Run the whirlpool for 5 to 10 minutes. Then shut off the whirlpool and drain the water.

If desired, rinse the bath surfaces with water.

Clean bath surfaces as needed with recommended cleaners.

CARE TIP

Sterling recommends the use of mild cleansers for weekly cleaning of your bath or shower made of solid Vikrell material.

PRODUCTS TO CONSIDER

- Cinch Streak Free Multi-Surface Cleaner
- Fantastik Antibacterial Heavy Duty
- Lysol Disinfectant Mildew Remover with Bleach
- Scrub Free Mildew Stain Remover
- Super Iron Out Multi-Purpose Rust Stain Remover